

SCHEMA TECNICA

BAMBU'

Tit. 1300 100% Cotone Mercerizzato (CO)

Impiego: Macchina rettilinea finezza 3 ad un capo

Colori: Cartella realizzata con colori tinti in matasse.

Istruzioni di lavaggio:

Si consiglia di lavare a secco con il solvente indicato. In caso di lavaggio ad acqua usare una temperatura massima di 30°C e saponi Neutri non ammorbidenti. Per maglieria rigata con tinte forti lavare a secco.

Avvertenze:

- Evitare l'asciugatura in centrifuga. Asciugare su piano orizzontale. Non torcere il capo.
- E' indispensabile lavorare a 2 o più guida fili.
- Essendo un filato fantasia deve essere tollerato uno scarto medio del 4% - 5 % per imperfezioni tintoriali e di struttura.

Etichettatura:
per maglia UNITA:



per maglia RIGATA:



Importante:

In caso di **riparaffinatura** del filato utilizzare bassa velocità per ottenere rocche morbide e soprattutto di densità uniforme. All'inizio della lavorazione **controllare** attentamente i primi teli ed in caso di irregolarità del prodotto avvertire immediatamente l'ufficio tecnico di FILOBEL per l'eventuale sostituzione

In ogni caso la filatura non può riconoscere danni sul prodotto già lavorato.

BAMBU'

Count 1300 100% Mercerized Cotton (CO)

Use: yarn to be used at one end on 3 gg flat-knitting machine.

Colours: Colour card realised with solid colours dyed on hanks

Washing Instructions:

We advise of washing with water, the temperature must not exceed 30°C and non-softening neutral soaps must be used. Bright-coloured striped knitwear should be dry-cleaned

Warnings:

- Do not spin dry. Dry on a flat surface. Do not twist the garment.
- It is necessary to work with 2 or more thread guides.
- Being a fancy yarn an average of 4% - 5% tolerance must be accepted for dyeing and structural faults.

Labelling:

For SOLID knits:



For STRIPED knits:



Important:

In the event of yarn **re-waxing**, use a low speed to obtain soft cones and above all uniform density. Please **check** carefully the first knitted fabrics and in case of unevenness, immediately notify the FILOBEL **technical department** who will authorise any replacement.

In any case, the spinning company cannot accept responsibility for damage on knitted panels.