

# SENSUALE

Tit.6800 96% Cotone - 4% Poliestere (Paillettes)

Impiego: Macchina rettilinea finezza 5 ad un capo.

Colori: Cartella realizzata con l'utilizzo di colori PRE-TINTI ,

## Istruzioni di lavaggio:

**LAVARE ESCLUSIVAMENTE A SECCO**

Bisogna assolutamente evitare la CENTRIFUGA

## Avvertenze:

- E' indispensabile lavorare a 2 o più guida fili .
- Essendo un filato fantasia deve essere tollerato uno scarto medio del 4 % - 5 % per imperfezioni di struttura.
- Per la lavorazione ricordarsi che le paillettes vanno sempre sul rovescio
- Si consiglia di lavorarlo in abbinamento ad altro filato (INGANNO)

## Etichettatura:

per maglia UNITA:



per maglia RIGATA:



## Importante:

In caso di ri paraffinatura del filato utilizzare bassa velocità per ottenere rocche morbide e soprattutto di densità uniforme. All'inizio della lavorazione controllare attentamente i primi teli ed in caso di irregolarità del prodotto avvertire immediatamente l'ufficio tecnico di FILOBEL per l'eventuale sostituzione.

**In ogni caso la filatura non può riconoscere danni sul prodotto già lavorato.**

# SENSUALE

Count 6800 96% Cotton - 4% Polyester (Paillettes)

Use: Single-fabric flat-knitting machine, yarn count 5

Colours: Colour card realised with pre-dyed cols.

## Washing Instructions:

**ONLY DRY CLEAN**

It's necessary to avoid the spin -dryer

## Warnings:

- It is very important to work with 2 or more thread guides.
- Being a fancy yarn an average of 4 % - 5 % tolerance must be accepted for structural faults.
- During knitting, Please keep in mind that Paillettes have to be always on back.
- We suggest to work with other yarn (INGANNO)

## Labelling:

For SOLID knits:



For STRIPED knits:



## Important:

In the event of yarn re-waxing, use a low speed to obtain soft cones and above all uniform density. Please check carefully the first knitted fabrics and in case of unevenness, immediately notify the FILOBEL technical department who will authorise any replacement.

**In any case, the spinning company cannot accept responsibility for damage on knitted panels.**